


MicroGuard HVAC/R Warranty Verification Chart

COIL & FIN COMPARATIVE

To receive an Adsil HVAC/R Limited Warranty, Condenser Coils must be new units or field installed units less than 3 months old. For field units the condenser coil must also reflect a 'Fin Coil Rating' of 10 or 9.


WARRANTABLE COILS

Fin Coil Rating - 10



- Brand New Out of Box
- No Fin or Coil Corrosion
- Oil Residue is Visible

Fin Coil Rating - 9



- 3 Month Old or Less Field Unit
- No Fin or Coil Corrosion
- Some Surface Debris on Fins

NON-WARRANTABLE COILS


Fin Coil Rating - 8



Fin Coil Rating - 7



Fin Coil Rating - 6



Fin Coil Rating - 5



Fin Coil Rating - 4



Fin Coil Rating - 3



Fin Coil Rating - 2



Fin Coil Rating - 1



Fin/Coil Ratings between 8 & 1 are never eligible for an Adsil HVAC/R Limited Warranty.

Whereas ratings between 8 & 5 would benefit from MicroGuard AD35 protection, the unit would not be eligible for a warranty.