

Adsil®

PRESERVE | PROLONG | PROTECT



Case Study:

GAIDOS SEAFOOD RESTAURANT

3700 SEAWALL BLVD, GALVESTON, TX 77550

Phone: (409) 762-9625

Galveston, Texas Seawall is a highly corrosive coastal environment.

Situation:

Condenser coils were being replaced each year in this harsh, coastal environment. New American Standard equipment was treated with Adsil MicroGuard AD35 Coil & Fin Protective Treatment, in April of 2002. Cabinetry, screws, coils & fins and interior support metal were coated.

Result:

After eighteen months the coils/fins, cases, fan blades are all in excellent condition. Fins are attached to coil tubes resulting in the retention of conductive heat transfer and designed energy efficiency. Fins are pliable and can be bent with out breaking or cracking.



Cabinet shines like new!



No corrosion on the coil edges!