

MICROGUARD®

Concrete Surface Sealer

Corporate Headquarters
1901 Mason Ave, Suite 101
Daytona Beach, FL 32117

Toll Free: 800.549.2539
Phone: 386.274.1382
Fax: 386.274.1798
www.adsil.com

CASE STUDY: Industrial Bathroom Floor Solution Truck Manufacturing Plant – Elkhart, IN



Before Treatment



After treatment with MicroGuard® AD703

Location: Precision Industries Plant – Employee Bathroom; adjacent to paint spray booth.

Problem: Employees working in the spray booth were tracking paint overspray from epoxy, urethane and zinc-rich coatings onto the bathroom floors located adjacent to the spray booth. Maintenance could not remove the residues from these tracked coatings without also removing the epoxy floor paint.

Solution: Diamond grind floor surface to expose bare and stable concrete. Apply a self-leveling floor epoxy/quartz system to establish uniform base. Apply one coat of MicroGuard® AD703 Concrete Clear Gloss Treatment and allow to cure for 5 days.

Results: Paint residues can now be removed using methylene chloride based paint stripper and without damaging the MicroGuard® clear treatment. Stripper residues are then removed using MicroKleen™ PLC-1 Cleaner & Degreaser.

MICROGUARD®
Anti-Graffiti

MICROGUARD®
Corrosion Protection

MICROGUARD®
Tile Surface Sealer

MICROGUARD®
HVAC

MICROGUARD®
Concrete Surface Sealer

MICROGUARD®
Anti-Skid

Powered by:
Adsil
CORPORATION