

MICROGUARD[®]

Concrete Surface Sealer

Corporate Headquarters
1901 Mason Ave, Suite 101
Daytona Beach, FL 32117

Toll Free: 800.549.2539
Phone: 386.274.1382
Fax: 386.274.1798
www.adsil.com

CASE STUDY: Atlantic Beach, Florida Pool Deck



Before Treatment



After treatment with MicroGuard[®] AD703

Situation: Mexican tile pool deck was originally sealed by owner using an 'off-the-shelf', water-based, do-it yourself sealer product. The Water-Based Deck Coating turned white, became stained from spills, was very slippery, and resulted in a horrible appearance.

Solution: After stripping off the old sealer and cleaning the tile & grout, per Adsil published instructions, the deck was re-sealed using a two step process consisting of a first coat of MicroGuard[®] AD702 Sealer followed by a top coat of MicroGuard[®] AD703 Clear, which encapsulated the Microgrip[™] Anti-Skid Floor Media Additive.

Results: Photos show how good the final results are with the MicroGuard[®]/ Microgrip[™] Anti-Skid System.