

MICROGUARD[®]

Concrete Surface Sealer

Corporate Headquarters
1901 Mason Ave, Suite 101
Daytona Beach, FL 32117

Toll Free: 800.549.2539
Phone: 386.274.1382
Fax: 386.274.1798
www.adsil.com

CASE STUDY: Public Restroom Tile Flooring



Before Treatment



After treatment with MicroGuard[®]

Situation: Public restroom tile had a heavy wax build up in grout causing discoloration, making the floor appear dirty and unsanitary. Customer was not able to clean grout lines; cleaning was nearly impossible.

Solution: After proper cleaning, per Adsil published instructions, MicroGuard[®] AD703 Clear was applied using specified spray application method.

Results: White grout lines are sealed from stains and remain visually clean & fresh. Floor no longer requires waxing, stripping and re-waxing. Tile surface is less slippery, wet or dry, than the original, bare tile or the waxed tile floor. Appearance is visually appealing, again! Surface cleans easily with hot water and mild cleaner.